


ISSUES.

1. 27/4/55.
ON P.F.P: L1,L2 CHANGED. R43,R54,R69,R144, R149,R150 CHANGED.
2/13138 19/8/55.
ON M.O. PANEL: C12 CHANGED.
ON P.F.P: R100,R299 ADDED. C44,C45 ADDED.
3/13456 14/11/55.

NOTE.
RESISTORS 10% 1/4W UNLESS OTHERWISE MARKED.
CAPACITORS 350V.D.C. WORKING UNLESS OTHERWISE MARKED
CASE WIRING CONNECTIONS, SHEET 2.
DELAY LINE CONNECTION.
MR's ARE CV.448.
● VALUE ADJUSTED ON TEST.